

Montageanvisning

GERMINATOR

Montageanweisung

SP 3000


Assembly instructions

SP 5000

Instructions de montage


SP 6000

SP 7000




GERMINATOR

SP 4000



 **KONGSKILDE**

KONGSKILDE *Spare Parts List*



| Fig. | Pack | Serial no. | Part no. | Pieces | Notes |
|------|------|------------|-------------|--------|--------------------------|
| 1 | | | 100 315 003 | 8 | M12 |
| 2 | | | 100 331 007 | 8 | M12 |
| 3 | | | 101 200 350 | 2 | |
| 4 | | | 101 200 347 | 2 | |
| 5 | | | 101 000 064 | 2 | |
| 6 | | | 101 200 340 | 2 | |
| 7 | | | 101 200 352 | 1 | |
| 8 | | | 100 316 031 | 8 | M14 |
| 9 | | | 100 306 055 | 2 | M16 x 40 mm |
| 10 | | | 101 200 334 | 1 | |
| 11 | | | 100 308 016 | 8 | M14 x 40 mm |
| 12 | | | 101 200 603 | 4 | |
| 13 | | | 101 200 339 | 1 | |
| 14 | | | 101 200 356 | 1 | |
| 15 | | | 101 200 338 | 1 | |
| Cpl: | | | 101 000 507 | 8 | Fig. 16 + 17 |
| 17 | | | 100 315 003 | 8 | M12 |
| 23 | | | 101 000 740 | 8 | SQ tine with ultra share |