



VIBRO MASTER 2500



- Ⓒ GB Spare parts list
- Ⓒ PL Katalog części zamiennych
- Ⓒ DK Reservedelsliste


Tab. 1



Tab. 1

Fig.	Serial no.	Part no.	Pieces	Notes
1		300316011	8	Self locking nut M20
2		310003553	1	Busch
3		71000180109	1	Chain
4		300304109	8	Screw M20x60
5		310152700	1	Linch pin
6		310121900	1	Headstock cpl
7		310146500	2	Arm
8		300304113	1	Screw M24x200
9		7205302018	3	Nut M24
10		300304116	4	Screw M20x55
11		310146600	1	Central frame
12		101110 004	1	Wheel arm right
13		101110005	1	Wheel arm left
14		71918835700	2	Bolt 32x240
15		101110016	4	Spindel
16		310003365	2	Hook
17		300316020	4	Self locking nut M10
18		300002074	2	String
19		300304239	2	Imbus screw M10x35
20		300304215	2	Screw M20x45
21		300304157	4	Screw M8x35
22		7202001001	2	Rope pulley
23		300315018	2	Self locking nut M8
24		310158800	1	Frame for pulley
25		300304156	2	Screw M8x30
26		100423081	1	Axle ø40x235
27		100423036	4	Seal cover Z007
28		100401030	1	Ball bearing 6206
29		100423062	1	Spacer ø35/31x64,6mm
30		100423073	2	Rim
31		100401028	1	Ball bearing 6205
32		100423064	1	Flat washer ø40x/17 x 3mm
33		300316023	1	Lock nut M16
34		100423065	1	Dust cap M62 x 1mm
35		100423071	1	Tube 24x8.00-14.5
36		100423070	1	Tyre
37		310160400	1	Wheel cpl 24x8.00-14.5
38		100316005	4	Lock nut M12
39		300304058	4	Set screw M12x40
40		101110137	4	Wheel arm axle spacer
41		100381018	4	Flat washer 1"
42		101110415	4	Tube
43		101090199	4	Frame bush
44		101091034	4	Crank handle spring
45		300304034	8	Set screw M10x30
46		300316023	4	Lock nut M16
47		300304093	4	Set screw M16x45
48		310003508	2	Scrapter


Tab. 2



Tab. 2

[illegible]

Tab. 3




Tab. 3[illegible]

Tab. 4

Rotocrats type: RD-VM


For Cultivators type:




Tab. 4

Rotocrats type: CD-VM

For Cultivators type:




Tab. 5




Leveling bars type: LB-VM

For Cultivators type:



Tab. 5[illegible]

Tab. 6



Tab. 6

[illegible]

